

---

349-44	Tuscor- Abandon Br. 63	11207
757-44	Oden(near) Filling Bridge No. 109	10950
612-47	Thos.Falls - Rebuild Br. 36 - Progressive Compl Report)	11527
612-47	"	Rebuild Br.36-Final Report

- 30 28 Re: Bridges 94, 94.2, and 96 - repairs & 1/4 Ballast  
30 SAE-VCB distance. E.E. Bridge #94 at Clarks Fork to  
(H.B. of 2nd track So..
- 30 Re: Soundings thru swamp structure on left side track  
(Bridge 109.
- 14 AFE 757-44 Re: Est. of cost of filling Bridge 109 near ODEN  
30 Re: Prop. line change East of Bridge 36 - Plat - 5 1/2 M.W. of <sup>1944</sup>  
30 Re: HMT-SAE raising track Bridge 94.2 (Thomp. Falls.  
30 Proposed Line change West of Thompson Falls - Bridge 36  
30 Re: Ravine Section of Bridges 94 on Main Line & siding  
(and of Bridge 94.1 over Lightning Creek.
- 22 Re: Survey for Line Change - Curve 98 - SAE; VCB.  
30 Est. cost of filling Bridge #63 - AFE-349-44  
30 Survey Acct. Shims E.E. Bridge #60 - nr. Tusson
- 9 WASHOUT: 3 1/2 Mi. <sup>→ (Plat in steel drawer No. 2)</sup> West of HERON - near Bridge #83  
30 TIE FRAMING DATA - BRIDGE 102 - near Strong Creek  
5 The extension of concrete arch at MP 101 1/2  
(2195 - near Denton.

- 30 Tables of soundings below top of tie of Bridges  
on the Idaho Div.-East of Cheney - 1938.
- 30 ~~Water levels in Lake Pend Oreille~~  
Reinforcing Bridges 3.2 & 4 on Idaho Division
- 30 Re: Spalling of concrete shaft in Pier No. 7 of  
(Bridge No. 55 - 1st subdivision.
- 30 Re: Contract for Painting Steel Bridges with A.H.  
(Barbour & Son. - Amount, type and recommenda-  
(tions for Paint for Bridges Nos. 36, 50, 55, 60,  
(92, 94.1 - Daily Reports of Work Progress &  
(Paint Shipments - 1945
- 30 Re: Proposal for painting Bridges on the Ida.Div.  
(&Rocky Mtn. Divisions - 1945.
- 30 Re: Painting of Bridges on Ida.Div. by A.H.Bar-  
(Bour & Son - Payroll Sheets - 1945
- 30 Re: Fire at Bridge #50(Beaver Creek) July 12, 1945
- 30 Re: Prop. R.C.P. Culvert 24"-24' - Cabinet - M.P.  
88+552 - X-Index Cabinet
- 30 Br. #50-Plan for encasing shoe of bent 10.

- 30 161-45 Br. No. 26-Steel span replacing W. App.  
30 Br. 36 nr. Thompson Falls - Repairs  
30 Br. 92 nr. Clark's Fork - Prop'd. Line  
Change & New Bridge  
30 Br. 69 Concrete slabs and curbs (nr. Noxon)  
30 Br. 60 Tie Framing - F.B. 310 - p.81  
9 Data on Br. 83 nr. Heron  
30-10 (General Bridge Inspection - Levels - Br. 36  
(Ravine Section - 10-'46  
30-10A Test Piles for Center Pier - 10-'46 Br. 36  
30 Levels for tie-framing of Br. 107, Pack River  
30 Bridge and Culvert Record- Completed 5/3/47  
30-10B Construction of Center Pier Br. 36  
30 Bridge #78 (nr Heron over Elk Creek)  
30 Br #94.1 Tie Framing Levels  
30, A, B, C, D, E, Construction of Center Pier at Bridge 36  
F, G and Line Change in Connection with the  
rennovation of Bridge 36

30 Tie Framing Levels for Br60 IdalstSub.  
30 Base of Rail Profile Br. 96  
30 Tie Plan Br. 94.1 Over Lightning Creek.