

ATLAS SPUR

A.F.E.	E.D.	F.C.R.	DESCRIPTION.
232-C-34	17-34	8281	Replace Highway Culvert at M.P. 8+4980°.
480-47	89-47		Spur to serve Sather and Son. (Doc. 19521 3-27-47)
44-49	11-49	11817	Remove Trackage.
510-57	61-57	14051	Rehabilitate & Extend Spur Serving Atlas Tie Co.
591-57	72-57	14065	Sale of Portion of Interchange Track to Atlas Tie Co.