

QUENDALL, WASHINGTON

## Tacoma Division.

A.F.E.	E.D.	F.C.R.	DESCRIPTION.
353-33	89-33	11487	Rebuild Bridge # 6 and remove portion of Siding.
414-34	104-34	11767	Riprap Bridges # 6 and 9.
208-35	69-35	11983	Walk on North Side of Bridge # 6.
388-38	107-38	13337	Drain and Culvert at M.P. 8/2854
24-41	12-41	13826	Sump at Culvert at M.P. 8/2854
613-48	131-48	15684	Trackage to serve Barbee Mill Co. (Doc.19988 - 5-24-48 & 7-13-48 )
497-49	88-49	15923	Install Drain and Fill ditch to prevent Slides at M.P. 8/2854'.
574-53	125-53	16796	Correct Slide Conditions.
364-55	66-55	17282	Trackage to serve Puget Timber Co. ( Doc 22233 - Hoving File # 1257-2 )
507-55	91-55	17283	Additional trackage to serve Puget Timber Co. ( Doc. 22310 )
51-56	20-56	17284	Additional trackage to serve Puget Timber Co.
185-63	30-63	20032	Fill Srg. No. 6.1/.

