

A.F.E.

EDDY

IDA. 1st. Sub.

645-A-46 (F.B.341) REmove Eastward Siding (7103 Data) 11318

15-47 (F.B.310) Relayspur track 11410

Eddy

File No.

Subject

6

Slide Condition nr Eddy at MP25+3016

File

AFE

EDDY- Ida. Div. 1st Sub.

29

645-A-46

15-47

Slide at MP 17+2700

Remove Eastward siding

Relay spur track

6

Slide conditions nr. Eddy at MP 25+3016