

<b>N.P.R.Y.</b>			
<b>IDAHO DIVISION</b>		<b>DISTANCE SCHEDULE</b>	
<b>SEATTLE AND ADRIAN BRANCHES</b>			
<b>SEATTLE BRANCH</b>		<i>Distance between</i>	<i>Distance from Davenport</i>
DAVENPORT	Wash. Central Branch Conn. .... H.B.(2169+59 = 0-05 <sup>2</sup> ) To OMANs .....	6.942	<u>0.000</u>
	Line betw. Val. Sec. #12 and #13 ..... (23+29 <sup>4</sup> )		0.442
			Val. Sec.      Wash. #12 Wash. #13
OMANs	Station Sign ..... (366+46) To ELEANOR .....	10.831	<u>6.942</u>
	FRY ... Spur ..... H.B.(462+66)		8.764
	GRAVELLES... Station Sign ..... (586+86 <sup>2</sup> )		11.116
ELEANOR	Station Sign ..... (938+35 <sup>2</sup> )		<u>17.773</u>
	End of Branch ..... (946+35)		17.924
<b>ADRIAN BRANCH</b>			<i>Distance from Odair</i>
ODAIR	Wash. Central Branch Conn. .... H.B.(5592+36 <sup>2</sup> = 0-01) Station Sign ..... (22+14) To BACON .....	10.327	<u>0.000</u> <u>0.419</u>
	Wye Conn. .... H.B.(63+70 <sup>2</sup> )		1.208
	Yard Limit Sign ..... (79+06)		1.320
	T.E. Connolly Inc Spur ..... H.B.(243+18 <sup>2</sup> )		4.606
BACON	Station Sign ..... (567+36) To ADCO .....	9.030	<u>10.746</u>
	Winston-Utah Constr. Co. Steel Yard Spur ... H.B.( 982+70 )		18.612
	Winston-Utah Construction Co Cement Spur. H.B.(1023+56 )		19.386
ADCO	Connell Northern Branch Conn. .... H.B (1044+15 <sup>4</sup> ) To ADRIAN .....	0.543	<u>19.776</u>
ADRIAN	End of N.P.Ry. and beginning of G.N.Ry. .... (1072+80 <sup>2</sup> )		<u>20.319</u>