

N.P.RY.
YELLOWSTONE DIVISION **DISTANCE SCHEDULE**
GLENDIVE EAST LINE

			<i>Distance between</i>	<i>Distance from Glendive</i>	
GLENDIVE	Main Line Conn.	H.B.(69+94 ² = 14+06)		<u>0.000</u>	
	To STIPEK	(0+00 = 16474+99 ⁴)	9.572		
	Line betw. Val. Sec. #1 and #6	(16465+24 ³)		0.451	Val. Sec. <u>Mont. #1</u> <u>Mont. #6</u>
	Redwater Branch Conn.	H.B.(16442+04 ³)		0.890	
	Yard Limit Sign - Glendive	(16384+47)		1.981	
GLENDIVE PIT	Gravel Pit	H.B.(16370+51 ²)		2.245	
WEST GLENDIVE	Spur to Industrial Site	H.B.(16327+72)		3.056	
STIPEK	Center of Telegraph Office	(15983+64 ³)		<u>9.572</u>	
	To INTAKE		9.233		
					15902+69 ³ = 15903+00 ³
					15699+56 ⁴ = 15695+56 ⁴
INTAKE	Station Sign	(15499+84)		<u>18.805</u>	
	To BURNS		8.648		15407+75 = 15407+82 ³
	DUELL Sugar Co. Spur	H.B.(15232+82 ⁵)		23.861	
	Line betw. Dawson and Richland Counties	(15150+76 ²)		25.415	15140+00 = 15142+23 ³
BURNS	Station Sign	(15040+92)		<u>27.453</u>	
	To SAVAGE		6.227		15019+99 ⁶ = 15020+06 ²
					14908+40 ³ = 14908+47 ²
	COPE Holly Sugar Co Spur	H.B.(14811+94)		31.787	14784+15 ² = 14784+24 ¹
SAVAGE	Center of Depot	(14711+90)		<u>33.680</u>	
	To HOFFMANVILLE		4.788		14574+31 = 14574+45
HOFFMANVILLE	Center of Shelter Shed	(14458+97 ⁵)		<u>38.468</u>	
	To CRANE		4.814		
CRANE	Station Sign	(14204+80 ⁵)		<u>43.282</u>	
	To NEWLON		6.309		
	PICHE G.W. Sugar Co. Spur	H.B.(14069+80)		45.839	
NEWLON	G.N.Ry. Conn.	H.B.(13871+68 ⁵)		<u>49.591</u>	
	To SIDNEY		4.290		
	RIVERVIEW Spur	H.B.(13797+92)		50.988	
	Yard Limit Sign - Sidney	(13695+42)		52.550	
	Corporate Limit	(13661+03)		53.580	
SIDNEY	Center of Depot	(13645+18)		<u>53.881</u>	
	Corporate Limit	(13627+05)		54.224	
	End of N.P.Ry. and beg. of G.N.Ry. Track	(13617+92)		54.397	