

LAKE WASHINGTON BELT LINE.

11th Sub--Division.

Seattle Division.

A.F.E.	E.D.	F.C.R.	DESCRIPTION.
298-F-31	40-31	11097	1931 - Tie Plates and Tie Renewals - Black River to Woodinville.
810-D-31	76-31	11191	1931 - Culvert Work - Lake Wash. Belt Line.

TACOMA DIVISION.

213-H-32	10-32	11339	1932 - Tie Plates.
278-E-32	58-32	11260	1932 - Bridge Work.
159-G-32	32-33	11538	1933 - Tie Plates.
216-K-33	35-33	11488	1933 - Bridge and Culvert Work - Black River to Woodinville.
233-B-33	64-33	11389	Rip Rap Bridge # 2, near Renton.
127-D-34	27-34	11951	1934 - Bridge Work - between Black River and Woodinville.
199-E-34	15-34	11819	1934 - Tie Plates - between Black River and Woodinville.
199-F-34	15-34	11820	1934 - Tie Plates - between Black River and Woodinville.
49-A&B-35	Tel. Dep't. 5-35		Telegraph Work - between Black River and Woodinville.
49-C-35	Tel. Dep't. 5-35		Transfer Rectifier to Woodinville from Snoqualmie.
124-F-35	18-35	12125	1935 - Tie Plates - Lake Wash. Belt Line.
189-E-35	42-35	12245	1935 - Bridge Work.
183-J-36	19-36	12391	1936 - Tie Plates - Black River to Woodinville.
243-G-37	27-37	12805	1937 - Tie Plates - Lake Washington Belt Line.
298-D-38	66-38	13170	1938 - Bridge Work - Black River to Woodinville.
182-I-39	37-39	13433	1939 - Tie Plates in Connection with Tie Renewals.
116-G-38		13189	1938 - Tie Plates.
268-F-39	42-39	13338	Replace Culvert at M.P. 15+3477 - Northrup.
164-I-40	10-40	13694	1940 - Tie Plates.
327-F-41	37-41	13891	Rebuild Bridge 6.1 at Quendall.
323-C-42	76-42	14975	1942 - Bridge Work - Black River to Woodinville.
321-G-42	61-42		1942 - Tie Plates.
261-A&B-43	87-43	14589&14590	Relay Curves between Black River and Woodinville.
368-43	108-43	14586	Rebuild South portion of Bridge 11.
694-B-43	179-43	14470	Rail Anchors - Black River to Woodinville.
211-D-44	11-44	14735	Tie Plates between Black River and Woodinville.
320-44	70-44	14693	Fill Bridge 1 on 36" RCP.

LAKE WASHINGTON BELT LINE

11th Sub-Division  
Wash.Val.Sec'n. 8 A.

TACOMA DIVISION.

A.F.E.	E.D.	F.C.R.	DESCRIPTION.
321-44	71-44	14634	Fill Bridge # 3.
300-B-44	66-44	15044	Renew Bents Bridge 16 at Wilburton.
363-44	77-44	14694	Fill Bridge 3.2 on 48" RCP.
250-C&D-46	35-46	15242	Tie Plates - Black River to Woodinville.
59-47	14-47	15409	Relay Various Curves between Woodinville and Renton.
310-D-47	32-47	15911	Tie Plates - Black River to Woodinville.
430-F-47	63-47	15721	Renton; Abandon Culvert M.P. 4+737'. Abandon and Ditch Culvert M.P. 5+825'. Midlakes; Remove Culvert M.P. 13+1437'.
496-47	105-47	15459	Ballast Curves.
388-48	91-48	16779	Fill Bridge 2.1 at Renton. ( Cancelled )
831-A-48	183-48	15774	Patch Ballast at Woodinville and Bellevue.
194-B-49	26-49	15797	Tie Plates.
553-D-49	80-49	16372	Bridge and Culvert Work. Black River to Woodinville. Bridge 4, M.P. 9+4113 and Bridge 18.1 .
553-E-49	80-49	16080	Renew in Treated Material Bridge 9. Abandon RCP and Build Ditch at Woodinville
457-H-50	82-50	16236	Renew Stringers Treated at Bridge 11.1
551-G-50	119-50	16116	Tie Plates.
551-D-50	119-50	16167	Tie Plates.
68-A-51	6-51	16724	Relay Track with 100# Rail replacing 85# and 72#; Black River to Woodinville.
68-B-51	6-51	17029	Relay Track with 100# Rail replacing 85# and 72#; Black River to Woodinville.
204-A-51	24-51	16435	Bank Widening and Ballasting: Woodinville to Black River.
204-B-51	24-51	16655	Bank Widening and Ballasting: Woodinville to Black River.
322-H-51	39-51	16619	Renew Complete, treated, Bridge 0.2 . Renew Stringers, Ties and Gurad Timber and Bulkheads, Treated Bridge 6.2 .
393-52	68-52	16732	Replace Bridge 10 at Factoria.
716-52	153-52	16640	Flashing Light Highway Crossing Signals at M.P. 1+4561' - Hollywood.
424-I-52	2-52	16628	Bridge and Culvert Work between Black River and Woodinville, Bridge 2.
472-53	77-53	16795	Relay Curve 8-B ; Quendall to Wilburton.
437-C-53	2-53	16885	Bridge 0.1 Renew Stringers. M.P. 15+2625', and 18-4518' Replace VP with RCP. Bridge 23, Drive new Bents.

## TACOMA DIVISION.

A.F.E.	E.D.	F.C.R.	DESCRIPTION.
53-B-54	7-54	16813	Rail Anchors - between Black River and Woodingille.
301-54	54-54	16898	Culvert at M.P. 8+958'; near Quendall.
239-F-55	2-55	17191	M.P. 16+3800' - Replace VP with RCP.
267-58	Tax Dept. #1251		Assessment for Watermains, Utility L.I.D. No. 1, King County Water Dist. No. 92.
366-58	87-58	17987	Relay Curves - Black River to Woodinville.
443-59	86-59	18342	Relay Curves - Black River to Woodinville.
228-E-60	2-60	18754	Bridge & Culvert Wk. - Black River to Woodinville. Brgs. 0.1, 6, 6.2.
404-60	82-60	18843	Relay Curves - Black River to Woodinville.
302-61	46-61	19042	Relay Curves - Quendall to Kirkland.
480-62	83-62	19459	Relay Curves - Quendall to Kirkland.
272-63	44-63	19563	Relay Curves - Renton to Woodinville.
367-64	60-64	20037	Relay Curves - Between Black River & Woodinville.
316-65	53-65	20295	Relay Curves - Black River to Woodinville
199-66	29-66	20946	Relay Track...Black River and Woodinville
199-A	29-66	20723	Relay Track...Black River and Woodinville
223-N-66	2-66	20475	Replace RSB with RSB...Wash. St. Line to Pendleton
225-E-66	2-66	21021	Bridge #16, Redrive Bents...Black River to Woodinville
366-67	85-67		Widen Boeing Access Road O.H.Xing MP6+4843 Seattle and Black River.
A.F.E.	E.D.	BEGUN-COMPLETED	DESCRIPTION
110-68	15-68		Btw. Houghton and Kirkland:Rebuild Bridge No. 16.