

N O R T H E R N P A C I F I C R A I L W A Y C O M P A N Y

OFFICE OF GENERAL MECHANICAL SUPERINTENDENT

DISTRIBUTION OF POWER

F E B R U A R Y 1, 1949 \_ \_ \_ \_

---

The following changes were made in assignment of locomotives during the month of January.

Idaho Division locomotive No. 1507, which was leased to Camas Prairie RR, was sent to South Tacoma Shop, and was replaced by Tacoma Division locomotive No. 1618, and assignment of latter locomotive changed to Idaho Division. The assignment of Locomotive No. 1507 was changed to Tacoma Division, where it will be sent when turned out of South Tacoma Shop.

Total number of locomotives assigned 794.

---

G.L.Ernstrom

General Mechanical Superintendent.

DISTRIBUTION OF POWER

SUMMARY

February 1, 1949.

<u>Division</u>	<u>Total Assigned</u>	<u>Total on Division</u>	<u>Leased</u>	<u>Engines Stored in Serviceable Condition</u>	<u>Engines Stored Unserviceable Waiting Disposition</u>
Lake Superior	101	101	-	6	11
St. Paul	119	119	-	-	1
Fargo	76	76	-	4	2
Yellowstone	86	84	2	7	3
Rocky Mountain	108	108	-	23	1
Idaho	120	111	9	15	9
Tacoma	184	181	3	23	6
<hr/>					
<u>Total</u>	<u>794</u>	<u>780</u>	<u>14</u>	<u>78</u>	<u>33</u>

DISTRIBUTION OF POWER

February 1, 1949.

The following changes were made from the January 1st, 1949. Distribution of Power List

Lake Superior Division.

CA# 1061 L9	Duluth	Swit.
CA# 1062 L9	Duluth Stored	Swit.
CA# 1068 L9	Brainerd	Swit.
CA# 1113 L9	Duluth	Swit.
CA 1212 Y3	Duluth	Swit.
C% 1632 W		Frnt.
1642 W		Frnt.
CAH% 1702 W3		Frnt.
CA% 1740 W3	Duluth	Swit.
C% 1758 W3	Wtg. Disposition	Frnt.
CA% 1764 W3	Brainerd Shop	Frnt.
CAH% 1774 W3		Frnt.
C% 1833 W3	Wtg. Brainerd Shop	Frnt.
CAH% 1849 W5		Frnt.
C 2166 Q3		Pass.
CH% 2234 Q5	Duluth Shop	Pass.
# 2413 T	Bemidji	Swit.
C# 2424 T	Brainerd Shop	Swit.

Fargo Division

C 26 Y1	Jamestown Shop	Swit.
CA% 1573 W		Frnt.
C% 1664 W1		Frnt.
CA% 1688 W1	Wtg. Livingston Shop	Frnt.
C% 1737 W3	Brainerd Shop	Frnt.
C% 1769 W3		Frnt.
C 2180 Q4		Frnt.
C 2182 Q4		Frnt.
C 2223 Q4		Frnt.

St. Paul Division

CA# 1088 L9	Stillwater	Swit.
CA 1162 L10	St. Paul	Swit.
C 1172 Q1	Wtg. Brainerd Shop	Swit.
C% 1504 W	Wtg. Brainers Shop	Frnt.
C% 1519 W	Shop Staples R.H.	Frnt.
CA 1540 W	Staples	Swit.
oC% 1825 W3	Wtg. Brainerd Shop	Frnt.
CAH% 1850 W5		Frnt.
CA% 1857 W5		Frnt.
C 2156 Q3	Brainerd Shop	Frnt.
C 2169 Q3		Pass.
C 2218 Q4	Wtg. Brainerd Shop	Frnt.
CAH% 2252 Q6		Pass.
CA% 2254 Q6	Wtg. Brainerd Shop	Pass.
CAH% 2255 Q6		Pass.
CAH% 2662 A3	Livingston Shop	Frnt.

Yellowstone Division

C 1530 W	Stored Glendive	Work.
C% 1710 W3	Livingston Shop	Frnt.
C% 1717 W3	Stored Glendive	Frnt.
C% 1718 W3		Frnt.
CA% 1720 W3	Stored Laurel	Frnt.
C% 1730 W3		Work.
CH% 1736 W3		Frnt.
CA% 1746 W3		Frnt.
C% 1828 W3		Frnt.
C 2501 W4	Glendive	Swit.
oCAH% 5008 Z5	Booster	Frnt.

DISTRIBUTION OF POWER

February 1, 1949.

The following changes were made from the January 1st, 1949. Distribution of power List.

Rocky Mountain Division.

Tacoma Division.

20 Y1	Butte	Swit.
1202 Y3	Shop Butte R.H.	Swit.
C 1387 S4	Stored Missoula	Frnt.
C%1624 W		Pass.
CA%1638 W	Shop Helena R.H.	Pass.
*C%1815 W3		Frnt.
CA%1855 W5		Frnt.
CA 2212 Q4	Stored Parkwater	Pass.
*CAH%2604 A	Stored Missoula	Pass.
CAH%2606 A	Stored Missoula	Pass.
CAH%2607 A	Stored Missoula	Pass.
oCAH%2611 A	Stored Missoula	Pass.
CAH%2665 A3		Pass.
CA%4021 Z3		Frnt.
oCH%5122 Z7		Frnt.
oCH%5123 Z7		Frnt.
oCAH%5124 Z7		Frnt.
oCH%5125 Z7		Frnt.
oCH%5135 Z8	Stored Livingston	Frnt.

# 1045 L9	Stored Tacoma	Swit.
CA 1049 L9	Stored Tacoma	Swit.
OB# 1053 L9	Stored Centralia	Swit.
CA 1070 L9	Stored Tacoma	Swit.
OB 1074 L9	Chehalis	Swit.
CA 1080 L9	Tacoma	Swit.
OB# 1082 L9	Tacoma	Swit.
1083 L9	Centralia	Swit.
OB 1091 L9	Tacoma	Swit.
CA 1104 L9	Stored Tacoma	Swit.
CA# 1110 L9	Aberdeen	Swit.
CA 1128 L9	Centralia	Swit.
1256 Y2	So. Tac. Shop	Swit.
CA 1350 S4	Stored Tacoma	Frnt.
CA 1364 S4		Frnt.
C 1381 S4		Frnt.
C 1384 S4	Stored Auburn	Frnt.
OB 1385 S4	Stored Tacoma	Frnt.
OB 1507 W	Wtg. So. Tac. Shop	Frnt.
C%1549 W		Work.

CA%1619 W	Stored Tacoma	Frnt.
OB 1621 W		Frnt. Mxd.
OB 1655 W		Frnt.
OB 1670 W1	Stored Tacoma	Frnt.
CA%1683 W1	Stored Auburn	Frnt.
CA%1685 W1	So. Tac. Shop	Frnt.
C%1693 W1	Stored Centralia	Frnt.
OB 1697 W1	Stored Tacoma	Frnt.
oOB 1706 W3	Stored Tacoma	Frnt.
*CA%1713 W3		Frnt.
OBH 1752 W3	Stored Tacoma	Frnt.
OBH 1766 W3		Frnt. Hlpr
C%1780 W3		Frnt. Hlpr
oCA%1784 W3		Frnt.
CAH%1791 W3	Stored Auburn	Frnt.
OB 1812 W3		Frnt.
CAH%1821 W3		Work.
CA%1826 W3	Stored Auburn	Frnt.
OBH 1829 W3		Frnt.
OB 2250 Q6	Stored Pasco	Pass.
CAH%2251 Q6		Pass.
OBH 2601 A	Shop Seattle R.H.	Frnt.
OBH 2608 A		Frnt.

Idaho Division

122 DE	Yardley	Swit.
C 1174 G2	Shop Pasco R.H.	Swit.
C 1358 S4		Work.
C 1360 S4	Stored Pasco	Frnt.
C 1366 S4	So. Tacoma Shop	Frnt.
C 1367 S4		Work.
C 1377 S4		Frnt.
C 1388 S4	Stored Pasco	Frnt.
OB 1507 W	Tfr. To Tacoma Divin,	Frnt.
C%1533 W	Shop Parkwater R.H.	Frnt.
C%1592 W		Frnt.
OB 1618 W	Tfr. Fr. Tacoma Divin.	
	Leased C.P.R.R. 1-22-49.	
C%1729 W3		Frnt.
C%1742 W3		Frnt.
CA%1748 W3	Shop Livingston	Frnt.
*CA%1794 W3		Frnt.
CA%1795 W3		Frnt.
C 2252 Q8	Shop Pasco R.H.	Pass.
C 2203 Q4	Wtg. Disposition	Pass.
CA 2213 Q4	Stored Parkwater	Pass.
C 2222 Q4	Stored Parkwater	Pass.
*CAH%5113 Z6		Frnt.
oCH%5117 Z6		Frnt.

DISTRIBUTION OF POWER

February 1, 1949.

The following changes were made from the January 1st, 1949.

Distribution of power List.

Rocky Mountain Division.

Tacoma Division.

20 Y1	Butte	Swit.
1202 Y3	Shop Butte R.H.	Swit.
C 1387 S4	Stored Missoula	Frnt.
C%1624 W		Pass.
CA%1638 W	Shop Helena R.H.	Pass.
*C%1815 W3		Frnt.
CA%1855 W5		Frnt.
CA 2212 Q4	Stored Parkwater	Pass.
*CAH%2604 A	Stored Missoula	Pass.
CAH%2606 A	Stored Missoula	Pass.
CAH%2607 A	Stored Missoula	Pass.
oCAH%2611 A	Stored Missoula	Pass.
CAH%2665 A3		Pass.
CA%4021 Z3		Frnt.
oCH%5122 Z7		Frnt.
oCH%5123 Z7		Frnt.
oCAH%5124 Z7		Frnt.
oCH%5125 Z7		Frnt.
oCH%5135 Z8	Stored Livingston	Frnt.

# 1045 L9	Stored Tacoma	Swit.
CA 1049 L9	Stored Tacoma	Swit.
OB# 1053 L9	Stored Centralia	Swit.
CA 1070 L9	Stored Tacoma	Swit.
OB 1074 L9	Chehalis	Swit.
CA 1080 L9	Tacoma	Swit.
OB# 1082 L9	Tacoma	Swit.
1083 L9	Centralia	Swit.
OB 1091 L9	Tacoma	Swit.
CA 1104 L9	Stored Tacoma	Swit.
CA# 1110 L9	Aberdeen	Swit.
CA 1128 L9	Centralia	Swit.
1256 Y2	So. Tac. Shop	Swit.
CA 1350 S4	Stored Tacoma	Frnt.
CA 1364 S4		Frnt.
C 1381 S4		Frnt.
G 1384 S4	Stored Auburn	Frnt.
OB 1385 S4	Stored Tacoma	Frnt.
OB 1507 W	Wtg. So. Tac. Shop	Frnt.
C%1549 W		Work.
CA%1619 W	Stored Tacoma	Frnt.
OB 1621 W		Frnt. Mxd.
OB 1655 W		Frnt.
OB 1670 W1	Stored Tacoma	Frnt.
CA%1683 W1	Stored Auburn	Frnt.
CA%1685 W1	So. Tac. Shop	Frnt.
C%1693 W1	Stored Centralia	Frnt.
OB 1697 W1	Stored Tacoma	Frnt.
oOB 1706 W3	Stored Tacoma	Frnt.
*CA%1713 W3		Frnt.
OBH 1752 W3	Stored Tacoma	Frnt.
OBH 1766 W3		Frnt. Hlpr
C%1780 W3		Frnt. Hlpr
oCA%1784 W3		Frnt.
CAH%1791 W3	Stored Auburn	Frnt.
OB 1812 W3		Frnt.
CAH%1821 W3		Work.
CA%1826 W3	Stored Auburn	Frnt.
OBH 1829 W3		Frnt.
OB 2250 Q6	Stored Pasco	Pass.
CAH%2251 Q6		Pass.
OBH 2601 A	Shop Seattle R.H.	Frnt.
OBH 2608 A		Frnt.

Idaho Division

122 DE	Yardley	Swit.
C 1174 G2	Shop Pasco R.H.	Swit.
C 1358 S4		Work.
C 1360 S4	Stored Pasco	Frnt.
C 1366 S4	So. Tacoma Shop	Frnt.
C 1367 S4		Work.
C 1377 S4		Frnt.
C 1388 S4	Stored Pasco	Frnt.
OB 1507 W	Tfr. To Tacoma Divin,	Frnt.
C%1533 W	Shop Parkwater R.H.	Frnt.
C%1592 W		Frnt.
OB 1618 W	Tfr. Fr. Tacoma Divin.	
	Leased C.P.R.R. 1-22-49.	
C%1729 W3		Frnt.
C%1742 W3		Frnt.
CA%1748 W3	Shop Livingston	Frnt.
*CA%1794 W3		Frnt.
CA%1795 W3		Frnt.
C 2152 Q3	Shop Pasco R.H.	Pass.
C 2203 Q4	Wtg. Disposition	Pass.
CA 2213 Q4	Stored Parkwater	Pass.
C 2222 Q4	Stored Parkwater	Pass.
*CAH%5113 Z6		Frnt.
oCH%5117 Z6		Frnt.

DISTRIBUTION OF POWER

February 1, 1949.

The following changes were made from the January 1st, 1949. Distribution of power List.

**Rocky Mountain Division.**

**Tacoma Division.**

20 Y1	Butte	Swit.
1202 Y3	Shop Butte R.H.	Swit.
C 1387 S4	Stored Missoula	Frnt.
C%1624 W		Pass.
CA%1638 W	Shop Helena R.H.	Pass.
*C%1815 W3		Frnt.
CA%1855 W5		Frnt.
CA 2212 Q4	Stored Parkwater	Pass.
*CAH%2604 A	Stored Missoula	Pass.
CAH%2606 A	Stored Missoula	Pass.
CAH%2607 A	Stored Missoula	Pass.
oCAH%2611 A	Stored Missoula	Pass.
CAH%2665 A3		Pass.
CA%4021 Z3		Frnt.
oCH%5122 Z7		Frnt.
oCH%5123 Z7		Frnt.
oCAH%5124 Z7		Frnt.
oCH%5125 Z7		Frnt.
oCH%5135 Z8	Stored Livingston	Frnt.

# 1045 L9	Stored Tacoma	Swit.
CA 1049 L9	Stored Tacoma	Swit.
OB# 1053 L9	Stored Centralia	Swit.
CA 1070 L9	Stored Tacoma	Swit.
OB 1074 L9	Chehalis	Swit.
CA 1080 L9	Tacoma	Swit.
OB# 1082 L9	Tacoma	Swit.
1083 L9	Centralia	Swit.
OB 1091 L9	Tacoma	Swit.
CA 1104 L9	Stored Tacoma	Swit.
CA# 1110 L9	Aberdeen	Swit.
CA 1128 L9	Centralia	Swit.
1256 Y2	So.Tac. Shop	Swit.
CA 1350 S4	Stored Tacoma	Frnt.
CA 1364 S4		Frnt.
C 1381 S4		Frnt.
C 1384 S4	Stored Auburn	Frnt.
OB 1385 S4	Stored Tacoma	Frnt.
OB 1507 W	Wtg. So. Tac. Shop	Frnt.
C%1549 W		Work.

**Idaho Division**

CA%1619 W	Stored Tacoma	Frnt.
OB 1621 W		Frnt.Mxd.
OB 1655 W		Frnt.
OB 1670 W1	Stored Tacoma	Frnt.
CA%1683 W1	Stored Auburn	Frnt.
CA%1685 W1	So. Tac. Shop	Frnt.
C%1693 W1	Stored Centralia	Frnt.
OB 1697 W1	Stored Tacoma	Frnt.
oOB 1706 W3	Stored Tacoma	Frnt.
*CA%1713 W3		Frnt.
OBH 1752 W3	Stored Tacoma	Frnt.
OBH 1766 W3		Frnt.Hlpx
C%1780 W3		Frnt.Hlpx
oCA%1784 W3		Frnt.
CAH%1791 W3	Stored Auburn	Frnt.
OB 1812 W3		Frnt.
CAH%1821 W3		Work.
CA%1826 W3	Stored Auburn	Frnt.
OBH 1829 W3		Frnt.
OB 2250 Q6	Stored Pasco	Pass.
CAH%2251 Q6		Pass.
OBH 2601 A	Shop Seattle R.H.	Frnt.
OBH 2608 A		Frnt.

122 DE	Yardley	Swit.
C 1174 G2	Shop Pasco R.H.	Swit.
C 1358 S4		Work,
C 1360 S4	Stored Pasco	Frnt.
C 1366 S4	So. Tacoma Shop	Frnt.
C 1367 S4		Work.
C 1377 S4		Frnt.
C 1388 S4	Stored Pasco	Frnt.
OB 1507 W	Tfr. To Tacoma Divin,	Frnt.
C%1533 W	Shop Parkwater R.H.	Frnt.
C%1592 W		Frnt.
OB 1618 W	Tfr. Fr. Tacoma Divin.	
	Leased C.P.R.R. 1-22-49.	
C%1729 W3		Frnt.
C%1742 W3		Frnt.
CA%1748 W3	Shop Livingston	Frnt.
*CA%1794 W3		Frnt.
CA%1795 W3		Frnt.
C 2252 Q8	Shop Pasco R.H.	Pass.
C 2203 Q4	Wtg. Disposition	Pass.
CA 2213 Q4	Stored Parkwater	Pass.
C 2222 Q4	Stored Parkwater	Pass.
*CAH%5113 Z6		Frnt.
oCH%5117 Z6		Frnt.