

N.P.RY.			
IDAHO DIVISION		DISTANCE SCHEDULE	
GENESEE BRANCH			
		<i>Distance between</i>	<i>Distance from Pullman Jct.</i>
PULLMAN JCT.	Palouse & Lewiston Branch Conn. H.B (4068+614 = 0+816)	0.000
	Station Sign (3+57)	<u>0.052</u>
	To STALEY	4.912	
	Yard Limit Sign - Pullman (49+64)	0.925
	Busby Spur H.B(97+22)	1.826
STALEY	Station Sign (262+906)	<u>4.964</u>
	To CHAMBER	2.359	
CHAMBER	Station Sign (387+48)	<u>7.323</u>
	To JOHNSON	2.486	
JOHNSON	Station Sign (518+74)	<u>9.809</u>
	To COLTON	5.219	
COLTON	Corporate Limit - Colton (776+85)	14.698
	Center of Depot (794+305)	<u>15.028</u>
	To UNIONTOWN	2.747	
	Corporate Limit - Colton (801+84)	15.171
UNIONTOWN	Corporate Limit - Uniontown (914+70)	17.308
	Center of Depot (939+353)	<u>17.775</u>
	To LEON	2.489	
	Corporate Limit - Uniontown (970+00)	18.356
LEON	Center of Shelter Shed (1070+768)	<u>20.264</u>
	To GENESEE	6.750	
	Line betw. Whitman Co., Wash., Val. Sec. #11 and Nez Perce Co., Idaho, Val. Sec. #5 (1074+917)	20.343
			State Line <u>Wash. #11</u> <u>Idaho #5</u>
	Line betw Nez Perce and Latah Counties ... (1372+00)	25.969
GENESEE	Corporate Limit - Genesee (1382+55)	26.169
	Center of Depot (1427+188)	<u>27.014</u>
	Corporate Limit - Genesee (1441+517)	<u>27.286</u>
	End of Branch (1460+285)	27.641