

N.P.RY.
IDAHO DIVISION **DISTANCE SCHEDULE**
SIMCOE BRANCH

		<i>Distance between</i>	<i>Distance from Toppenish</i>	
TOPPENISH	Main Line Conn. H.B.(3830+67 ⁸ = 0-5002 ⁵) To YETHONAT	3.242	<u>0.000</u>	
	Line betw. Val. Sec. #2 and #21 (15+00)		1.232	Val. Sec. <u>Wash. #2</u> Wash. #21
YETHONAT	Station Sign (121+16 ³) To ASHUE	2.944	<u>3.242</u>	
	UTAHCO ... Center of Siding (178+00 ⁴)		4.319	
ASHUE	Station Sign (276+63) To FARRON	2.930	<u>6.187</u>	
	VENNER ... Williams Bros Spur H.B.(395+06)		8.430	
FARRON	Station Sign (431+34) To HARRAH	1.099	<u>9.117</u>	
	Corporate Limit - Harrah (477+18)		9.985	
HARRAH	Center of Depot (489+37 ²) To BROWNSTOWN	3.077	<u>10.216</u>	
	Corporate Limit - Harrah (499+22)		10.402	523+06 ³ = 503+65 ⁵ 542+02 ³ = 542+03 ² 608+75 ⁶ = 608+77 ³
BROWNSTOWN	Center of Depot (632+45 ³) To WHITE SWAN	6.672	<u>13.293</u>	646+45 ⁵ = 646+46 ⁶
	RUPPLE ... Station Sign (698+38)		14.541	847+79 ⁶ = 846+30
WHITE SWAN	Center of Depot (983+25)		<u>19.965</u>	
	End of Branch (991+22)		20.116	