

FORT SHERMAN BRANCH

Idaho Division
5th Sub.

A.F.E.	E.D.	F.C.R.	DESCRIPTION.
410-E-31	34-31	7726	Braces on Bridges # 1 and 10. (between Hauser and Coeur d' Alene)
880-31	57-31	7836	Fill Bridge # 1.1
215-C-33	17-33	8100	Tie Plates on Bridge #1, Blackwell Spur.
215-D-33	17-33	8152	Tie Plates on Bridge # 11.1
178-C-36	9-36	8903	1936 - Tie Plates - between Hauser and Coeur d'Alene.
242-C-37	25-37	8921	1937 - Tie Plates - between Hauser and Coeur d'Alene.
599-37	72-37	9133	Blackwell - Fill 8 Spans of Bridge # 10.
179-X-39	31-39	9603	1939 - Tie Plates.
272-39	44-39	9579	Fill Bridge # 1 at Hauser.
241-G-41	29-41	10080	1941 - Tie Plates between Hauser and Coeur d' Alene.
318-C-42	45-42	10359	1942 - Tie Plates.
201-C-43	55-43	14538	1943 - Tie Plates.
209-C-44	17-44	10791	1944 - Tie Plates.
490-B-45	56-45	11079	Bridge and Culvert Work.
491-B-45	57-45	11058	Tie Plates.
123-C-47	19-47	11292	Fill Bridge # 1.0 at Coeur d ' Alene.
480-47	89-47	11551	Spur to serve Sather and Sons. - M.P. 8 (Doc. 19521)
345-49	44-49	12227	Relay Curves between Post Falls and Coeur d' Alene.
512-52	68-52	12955	Relay Curves between Hauser Jct. and Coeur d'Alene. (above amended as 363' of 72# Rail. Feb. 11-53)

A.F.E.	E.D.	BEGUN-COMPLETED	DESCRIPTION
499-C-68	2-68		Hauser to Coeur d'Alene: Replace timber with steel bridge per Bridge Engineer's Plan 93504.

FORM 84-150 W