

LARSON, WASHINGTON

Tacoma Division

A.F.E.	E.D.	F.C.R.	DESCRIPTION.
646-37	143-37	13228	Remove Bloedel - Donovan Lumber Co. spur.
33-40	8-40	13494	Remove portion of Bloedel - Donovan Lumber Co's. spur.
312-40	60-40	13495	Remove spur # 6 in Mill Yard.
716-47	158-47	15393	Remove trackage serving the Columbia Valley Lumber Co.
131-60	27-60	19321	Track Changes at Larson Mill.(Canceled 10-25-62)