N.P.RY.

ST. PAUL DIVISION DISTANCE SCHEDULE

LITTLE FALLS AND DAKOTA BRANCH

		Distance	Distance from	
		between	Little Falls	
				We to 32 8 8 7 = 24 50 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
LITTLE FALLS	Main Line Conn. H.B.(5630+176 = 22+551)		0.000	10 PE
	Wye Conn. and Line betw. Val. Sec. 9 and 11 H.B(32+891=24+50)		0.196	Val. Sec. Minn.*9 Minn.*11 Wye, N. 85618+79 to H. B. 24+50 = 0.195 mi
	Yard Limit Sign - Little Falls (143+24)		2.445	
FLENSBURG	Center of Depot	Τ.05Τ	8.104	
SWANVILLE	Center of Depot (813+573) To Burtrum	4.586	15.141	
	Line betw. Morrison and Todd Counties (829+38 ⁶)		15.440	
BURTRUM	Center of Depot	4.419	19.727	
GREY EAGLE	Center of Depot (1289+065) To WARD Springs	3.532	<u> 24.146</u>	
WARD SPRINGS	Center of Shelter Shed (1475+546) To Sauk Centre	8.332	<u>27.678</u>	
	Line betw. Todd and Stearns County (1632+862)		30.657	
SAUK CENTRE	Center of Depot	10.834	<u>010,86</u>	
	G.N.Ry Conn. H.B.(1946+83) G.N.RyCtr. of grade crossing (1952+23) G.N.RyCtr. of grade crossing (1959+59)		36.604 36.706 36.845	

N.P.RY.

ST. PAUL DIVISION

DISTANCE SCHEDULE

LITTLE FALLS AND DAKOTA BRANCH

		Distance between	Distance from Little Falls	
		1		
	Line betw. Stearns and Pope Counties (2415+474)		45.480	
WESTPORT	Center of Depot		46.844	
	To VILLARD	4.936	40.574	
VILLARD	Center of Depot		51.780	
	To GLENWOOD	6.866		
	Becker County Sand & Stavel Co Trock (2877+373)		54.228	
	M.St.P.&S.Ste.M.Ry. Conn. H.B.(3075+255)		57.975	
GLENWOOD	M.St.P.&S.Ste.M.Ry Ctr. of grade crossing (3082+503) Center of Depot	8.817	58.113 58.646	
		0.01		
STARBUCK	Center of Depot (3576+211) To New Prairie	6.199	67.463	
NEW PRAIRIE	Center of Depot (3903+513)	4.104	73.662	
CYRUS	Center of Depot		77.766	
	To Morris	570.9	11.100	
	Line betw. Pope and Stevens Counties (4173+65)		877.8	
	Yard Limit Sign - Morris (4505+81)	·	85.069	
	State Agricultural School Spur		85.837	
Morris	G.N.Ry.Conn. H.B.(4571+15 = 0+00) Center of Depot (28+03)		86.307 86.838	
	End of Branch		86.844	