

N.P.RY.
YELLOWSTONE DIVISION **DISTANCE SCHEDULE**
DICKINSON — GLENDIVE

		<i>Distance between</i>	<i>Distance from Dickinson</i>	
DICKINSON	Center of Passenger Depot (5783+86 ⁴)		<u>0.000</u>	Val. Sec. N.D. #2
	To ELAND	4.493		5797+25 ² = 5797+08 ²
	Corporate Limit (5847+18)		1.202	
	Yard Limit Sign - Dickinson (5914+83)		2.483	5929+14 ² = 5929+19 ²
ELAND	Station Sign (6020+96 ⁵)		<u>4.493</u>	
	To SOUTH HEART	5.434		6227+86 ⁶ = 6228+16
SOUTH HEART	Center of Depot (6308+17 ³)		<u>9.927</u>	
	To BELFIELD	10.373		6376+78 ⁸ = 6376+91 ⁸ 6546+03 = 6546+29
BELFIELD	Corporate Limit - Belfield (6827+34)		19.745	
	Center of Depot (6856+67 ⁵)		<u>20.300</u>	
	To FRYBURG	5.681		
	Corporate Limit - Belfield (6881+98)		20.779	
	Line betw. Stark and Billings Counties... (6934+26 ⁵)		21.770	
FRYBURG	Center of Freight Shed (7155+18)		25.954	
	Center of Telegraph Office (7156+61)		<u>25.981</u>	
	To SULLY SPRINGS	5.285		7344+53 ³ = 7351+73 ⁵
SULLY SPRINGS	Station Sign (7442+85)		<u>31.266</u>	
	To MEDORA	8.243		7634+30 ⁶ = 7634+33 ⁴ 7762+70 ² = 7762+80 7846+67 ² = 7846+92 ⁵

N.P.R.Y.				
YELLOWSTONE DIVISION		DISTANCE SCHEDULE		
DICKINSON — GLENDIVE				
		<i>Distance between</i>	<i>Distance from Dickinson</i>	
MEDORA	Center of Depot (7878+49) To RIDER LITTLE MISSOURI Storage Spur H.B.(7931+13 ⁵) Line betw. Billings and Golden Valley Counties(8113+00)	5.493	39.509	
RIDER	Station Sign (8168+51) To DEMORES	5926	45.002	
DEMORES	Station Sign (8488+47 ³) To SENTINEL BUTTE	4.967	50.928	
SENTINEL BUTTE	Corporate Limit - Sentinel Butte (8729+60) Center of Depot (8753+32 ⁵) To BEACH Corporate Limit - Sentinel Butte (8778+30)	8.405	55.446 55.895 56.368	
	CHAMA Spur H.B.(8943+05 ⁶)		59.489	
BEACH	Yard Limit Sign - Beach (9125+90) Corporate Limit (9151+85) Ollie Branch Conn. (9169+43 ⁶) Center of Depot (9197+11 ²) To YATES Corporate Limit (9247+12) Yard Limit Sign (9259+40)	5.626	62.951 63.443 63.776 64.300 65.247 65.480	
	Line betw. Golden Valley Co., N.D., Val. Sec. #2 and Wibaux Co., Mont., Val. Sec. #1 (9329+75)		66.812	State Line N.D. # 2 Mont. # 1
YATES	Center of Shelter Shed (9494+29 ³) To WIBAUX	4.944	69.926	9479+73 ⁵ = 9479+83 ²

N.P.RY.
YELLOWSTONE DIVISION **DISTANCE SCHEDULE**
DICKINSON — GLENDIVE

		<i>Distance between</i>	<i>Distance from Dickinson</i>	
WIBAUX	Yard Limit Sign - Wibaux	(9678+79)	73.421	
	Corporate Limit	(9733+99)	74.466	
	Center of Depot	(9755+33 ³)	<u>74.870</u>	
	To BEAVER HILL	3.563		
	Corporate Limit	(9788+87)	75.505	
	Yard Limit Sign - Wibaux	(9793+89)	75.601	
				9820+80 = 9821+61
				9926+77 ⁴ = 9928+30 ⁵
BEAVER HILL	Station Sign	To HODGES (9945+77)	<u>78.433</u>	
		6.825		
	Line betw. Wibaux and Dawson Counties... (10223+89 ¹)		83.701	
HODGES	Center of Telegraph Office	(10322+47 ³)	<u>85.258</u>	10229+49 ⁶ = 10245+86 ⁷
		To IONA	4.942	
				10511+02 ⁴ = 10512+99 ⁷
IONA	Station Sign	To CURRY (10585+41 ¹)	<u>90.200</u>	
		10.050		10668+70 ⁵ = 10669+61 ²
				10760+97 ⁴ = 10764+28 ⁴
				10805+42 ¹ = 10805+44 ¹
	ALLARD Spur	HB. (10807+45 ³)	94.325	10847+71 = 10847+84 ⁵
				10988+04 ² = 10988+09 ³
CURRY	Station Sign	To GLENDIVE (11120+44)	<u>100.250</u>	
		5.100		11200+70 = 11204+63
				11272+39 ⁸ = 11272+28
GLENDIVE	Yard Limit Sign - Glendive	(11284+63)	103.287	
	Corporate Limit	(11338+19 ³)	104.301	
	Center of Passenger Depot	(11393+55 ¹)	<u>105.350</u>	