

Fargo Division Local Train Brief

Train: Nos. 951-952 Mandan North Local (13th Subdivision)

Frequency: Daily except Sunday

Purpose: To do local work Mandan to Killdeer and handle coal business from mines.

Traffic Handled: Local business and heavy mine business at all coal mines and power stations on Mandan North Branch.

Schedule:

951-1*	Monday	Depart Mandan	10:00 AM
		Arrive Zap	12:00 Noon
		Depart Zap	12:30 PM
		Arrive Glenharold	1:30 PM
		Depart Glenharold	2:00 PM
		Arrive Zap	3:00 PM
		Depart Zap	3:30 PM
		Arrive Beulah	3:45 PM
	Tuesday & Thursday	Depart Beulah	2:00 PM
		Arrive Zap	2:15 PM
		Depart Zap	2:45 PM
		Arrive Glenharold	3:45 PM
		Depart Glenharold	4:00 PM
		Arrive Killdeer	6:00 PM
Wednesday	Depart Killdeer:	2:00 PM	
	Arrive Glenharold	4:00 PM	
	Depart Glenharold	4:30 PM	
	Arrive Zap	5:15 PM	
	Depart Zap	5:45 PM	
	Arrive Beulah	6:00 PM	
952-1*	Friday	Depart Killdeer	2:00 PM
		Arrive Mandan	6:00 PM
951-2*	Saturday	Depart Mandan	10:00 AM
		Arrive Zap	12:00 Noon
952-2*		Depart Zap	1:00 PM
		Arrive Mandan	3:00 PM

Terminal Handling: Mandan make up train in station order. At other terminals they do their own switching.

Restrictions: See Special Instructions.

Grouping: Station Order

Terminal Connections: Mandan with through freight trains.

* These section numbers must be shown on reports to NORPAC.

Office of GST.
Revised 4/14/69