

## NORTHERN PACIFIC RAILWAY COMPANY AUTHORITY FOR EXPENDITURE YEAR 1929

SUPERINTENDENT'S NO.

No.

DEPT. No. ENGINEERING DEPT. No. A. F. E. NO.

n	al	02	t	a

Div. Main Line

TABLE ND

VAL. SEC. No. 2

Dakota Div. a	stribution to be made  Operating Expenses	in General Office  Profit and Loss	Net Operating Expenses	Net Profit and Loss	
Cost of property retired	12093 6455	***************************************	5638 2150		7788
Incidental costs			The second secon		
Total to Operating Expenses			STNENT	***************************************	645
Total to Operating Expenses  Total to Profit and Loss	· · · · · · · · · · · · · · · · · · ·	and the special specia	RENT ADJUSTMENT	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	
- Material and Supplies	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	6116	BEM: 19		
To Bills for Collection	化甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基		· Control of the Cont	2000	267
그는 아무리를 가지 않는데 그는 점에 나는 그들은 그들은 그들은 그를 가지 않는데 하는데 하는데 없다.		- 44	The state of the s		
To Other Accounts	t-Additions and Bel	terments	The state of the s	**************	1692
To Other Accounts  Net charge to investment account  Total of distribution	t-Additions and Ber		Post Adjustment	Slare of Work: No.	1692
To Other Accounts  Net charge to investment account  Total of distribution  Itel	t-Additions and Ber		ost Adjustment	Class of Work: No.	1692 3 V
To Other Accounts  Net charge to investment account  Total of distribution	t-Additions and Ber	Original C	ost Adjustment	Class of Works No.	

Mandan (Nr)

Location: Title

Relay Main Line Rail -

and

Reason:

Eighty-five pound and ninety pound rail between Main Line M.P. Eighty-five pound and ninety pound rail between Main line M.F.

197 plus 4824, and 199 plus 1447, Mandan bottom, is badly battered
and worn and should be renewed. This covers that portion of the
track between West end of Dakota Division and the West end of the second curve East thereof, the curve Just West of the Missouri River bridge. This rail was listed for relay following inspection by


It is proposed to proceed accordingly as per estimate and sketch Engineer of Track.


attached.

Work to be done by company force under charge of Superintendent. Checked and Entered President's Office Accounting to concentrate in the office of Division Accountant. Date January 2 19 29 Signature and Title: APPROVED 17 Machan General Superintende Mech. Supt., Supt. Telgh. or Signal Engr. MW. MAR 1 4 1929 COMPTROLLER'S RECORD OF NOTICE OF APPROVAL AND OF COMPLETION

Form No. 1345 issued...

.19..... Work begun





104691202MF 10459+30# P.C. 1238 - 100# R.E. Rail Laid 6832 - 90# Rail Removed Signal #1982 moved from 25174 to 25195.5 25+66 Signal 1983 To comestour 10416+435 MP