N. P. 1363

NORTHERN PACIFIC RAILWAY COMPANY AUTHORITY FOR EXPENDITURE

IJ	n	6	V	
YEA	п			

COMPTROLLER'S CUP

SUPERINTENDENT'S NO.

DEPT. NO. ENGINEERING DEPT. No. 36

A. F. E. NO.

421

DISTRICT STATE Minn.

VAL. SEC. NO. 1

8+	Paul	DIV.	Main	Line	BRANCH		
	IS PEOUES	TED	FOR A	NET EXPENDITURE	of \$ 2218	(N.P.	Proportion
AUTHORITI	13 Lindowa			to Comerci (office.)		

Accounting distribution as follows: (Distribution to be made in General Office.)

counting distribution as follows: (D	Distribution to be mad Operating Expenses	Profit and Less	Not Operating Expenses	Ret Profit and Loss	•
Cost of property retired	837	•	831		
Value of salvage	The state of the s	A property delication of the second control	167		- ,
Incidental costs					998
Total to Operating Expenses	***************************************	***************************************	***************************************	\$2.50 x 2.50 x 2.00 \$2.50 x 2.50 x 2.	-
t week.			63.5 (32.5)	My	. 8
10 Marana		2 100:	16 19		716
10 20110 101	· · · · · · · · · · · · · · · · · · ·	Oug.	The second secon		
To Other Accounts	a landalimenta esta esta cara cara cara esta cara esta cara esta esta esta esta esta esta esta est	- 5 C.O°	1 1 8 minus		1220
Net charge to investment accoun	nt-Additions and Be	- Market Co.	and the state of t		- 50 SHADAR
Total of distribution		***************************		applica (1996)	11

Class of Works No. 12

Joint facility contract reference: G.N.Ry. Dec. 31, 1908 and letter Geo.T. Slade, Gen.Mgr.
N.P. Ry. to J.M.Gruber, Gen.Mgr. G.N.Ry. June 17, 1909.

The focation is on this company's property. To secure rights, it will be necessary (G.N.Ry. 24.47).

St. Cloud, Minn. Location:

Replace Switch machines

Reasoni


Replace the warn out American switch machines of facing point switch 39, and derails 40 and 41 with improved machines and electrical cross protection. The American machines were installed in 1909. After this replacement there will only be stalled in 1909 and the old American machines and the old American machines and the old American machines left in the plant three (3) of the old American machines left in the plant.

From Wilson Avenue to the Great Northern home signal at the west junction, the signal wires are in trunking except under Wilson Avenue and Third Street where they are in conduit. During wet weather these wires become grounded account of lack of drainage at these locations. The wires in the lack of drainage at these locations. The wires in the trunking will be placed as aerial cable on cable posts about 15 feet from the nearest rail, and Parkway cable placed under the two said streets. These wires were placed in 1909 and by this change we expect 10 years' additional service.

Work to be done by company force under charge of Signal Engineer.

Accounting to concentrate in the office of Div. Acct., Engig. Dept. Signal Engr. pag 2/21/29 Signature and Title: APPROVED: Asst. Chief Engr. or Engr. Maint.of Way General Superintendent Mach. Sunt., Sunt. Teigh. or Signal Engr. Chief Enginee For Comptroller.

COMPTROLLER'S RECORD OF NOTICE OF APPROVAL AND OF COMPLETION _19..... Work finished



N.P.R.Y

St.Paul Div. Main Line.
Replace Three Switch Machines
and Rearrange Wire Run.

Office of Signal Eng'r - St Paul, Minn. Febr 15 12-3 Functions to be replaced shown thus:

Functions rearranged shown thus:

Valuation Section *9 Minn