



STATUS OF AUTHORITIES FOR EXPENDITURE

| A. F. E. No. | Acct. No. | Date | | Location of Project | DESCRIPTION OF PROJECT | Date Received | | EXHIBIT C C-1 D | Form 586 587 | Form 588 | Record | |
|-------------------|---------------|--------------------|---------------------|---------------------|---|------------------|-------------|--|--------------------|-------------|--------|------|
| | | Approved | Completed | | | Field Report | Cost Report | | | | Num. | Card |
| 818-12 | 53,57 | 5-17-12 | 6-1922 | System | Application and Alterations in Safety Appliances on Freight Cars and Work Equipment. | Received 2-15-23 | | 4-3-29 (Revised) 4-16-28 (Revised) 9-22-23 | | | | ✓ |
| 801-13 | 51 | 1-30-13 | 11-23-18 | System | Replace Westinghouse Brake Equipment on 334 Engines. In Engineering Report. | | | | | | | ✓ |
| 800-15 | 54 | 2-5-15 | 1-19-17 | System | Changing Electric Light Wiring in Passenger Cars to Two Circuit System. In Engineering Report. | | | | | | | ✓ |
| 823-15 | ✓ 53 | 5-11-15 | 7-7-21 | System | Reinforce 100 Steel Underframe Stock Cars | Received | Received | 4-3-29 (Revised) 4-23-28 (Revised) 5-17-22 | | | | ✓ |
| 884-15 | ✓ 53 | 11-20-15 | 6-1918 | System | Apply Steel Center Sills to 1000- 80M Capacity Box Cars | | | 4-27-31 | | | | ✓ |